

CERTIFICATE OF COMPLIANCE

Certificate Number 20160520-E172877
Report Reference E172877-20141031
Issue Date 2016-MAY-20

Issued to: CARLO GAVAZZI LTD
BLB042
BULEBEL INDUSTRIAL ESTATE
ZEJTUN ZTN 3000 MALTA

This is to certify that
representative samples of

MOTOR CONTROLLERS, MECHANICALLY-OPERATED
AND SOLID-STATE
See Addendum Page


Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 508 & CSA C22.2 No. 14-13; Industrial Control
Equipment

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160520-E172877
Report Reference E172877-20141031
Issue Date 2016-MAY-20

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Open Type Solid State AC;

RSWT 75mm series, 3 Phase Pump Softstarter:

RSW, followed by T, followed by 40 or 60, followed by 32, 37, 45 or 55, followed by E, F or G, followed by 0, F or G, followed by V0 or V1, followed by 0 or 1, followed by 0 or 1, followed by C or left blank, may be followed by suffixes.

RSGT 75mm series, 3 Phase Softstarter:

RSG, followed by T, followed by 40 or 60, followed by 32, 37, 45 or 55, followed by E, F or G, followed by 0, F or G, followed by V0 or V1, followed by 0 or 1, followed by 0 or 1, followed by C or left blank, may be followed by suffixes.

RSBT 75mm series, 3 Phase Compressor Softstarter:

RSB, followed by T, followed by 40 or 60, followed by 37, 45 or 55, followed by E, F or G, may be followed by F, G or left blank, followed by V5 or V6, followed by 0 or 1 or 2 or 3, followed by HP or left blank, followed by C or left blank, may be followed by suffixes.

RSBD 75mm series, 3 Phase Compressor Softstarter:


RSB, followed by D, followed by 40 or 60, followed by 55, 70 or 95, followed by E, F or G, may be followed by F, G or left blank, followed by V5 or V6, followed by 0 or 1 or 2 or 3, followed by HP or left blank, followed by C or left blank, may be followed by suffixes.

RSGD 75mm series, 3 Phase Softstarter:

RSG, followed by D, followed by 40 or 60, followed by 55, 70, 85 or 100, followed by E, F or G, followed by 0, F or G, followed by VX, followed by 0, 1, 2 or 3, followed by 0 or 1, followed by 0 or 1, followed by C or left blank, may be followed by suffixes.

Accessories for the RSWT/RSGT/RSBT 75mm: Finger Guards:

RFCG, followed by X6, may be followed by suffixes.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

